



ISATPHONE 2 (MODEL 2.1)

FIRMWARE V01.00.13

Release Notes

15.03.21

CONTENTS

1.	INTRODUCTION	2
2.	RECOMMENDATIONS FOR INSTALLATION	2
3.	PRE-REQUISITED FOR INSTALLATION AND ADVICE AFTER INSTALLATION	2
4.	INSTALLING ISATPHONE 2 (MODEL 2.1) FIRMWARE 01.00.13	2
5.	FIXES AND ENHANCEMENTS IN THIS RELEASE	2

1. INTRODUCTION

IsatPhone 2 (Model 2.1) firmware version 01.00.13 has now been released and is available for download. Please follow the link below: <http://www.inmarsat.com/support/isatphone-2-support/>.

Firmware version 01.00.13 supersedes the firmware version 01.00.12 that was released in October 2020.

2. RECOMMENDATIONS FOR INSTALLATION

This is a recommended firmware upgrade as it addresses an issue found in production which is not expected to impact the normal operation of IsatPhone 2 (Model 2.1) handset.

3. PRE-REQUISITED FOR INSTALLATION AND ADVICE AFTER INSTALLATION

In order to upgrade the handset's firmware you must have a PC running Windows 10, Windows 8, Windows 7 or Windows XP. The USB drivers and IsatPhone 2 firmware upgrade tool for IsatPhone 2 (Model 2.1) must be installed.

These can be found on the Inmarsat support website by visiting <http://www.inmarsat.com/support/isatphone-2-support/>

Please read the installation guides for the firmware upgrade tool and USB drivers which are also downloadable from the website.

4. INSTALLING ISATPHONE 2 (MODEL 2.1) FIRMWARE 01.00.13

To install IsatPhone 2 (Model 2.1) firmware 01.00.13:

- a) Ensure that USB drivers and the firmware upgrade tool are installed on your PC.
- b) Double click on Inmarsat's firmware upgrade tool and follow on screen instructions.

The firmware upgrade will take approximately 1 - 2 minutes. After installation, you can check the firmware version by switching on the phone and selecting Menu > Settings > About > Firmware version

5. FIXES AND ENHANCEMENTS IN THIS RELEASE

- GPS antenna SNR value going below lower range at -120 dB in Engg. mode in production testing.