

Document No.: RN-230203-01
Date: 3rd February, 2023
Classification: External
Attn: All Customers
Related Products: GX-NX Series
Subject: **GX-NX & GX NX 2 FW Release Note – V2.03.XXX**

Dear Valued Customers,

Intellian is pleased to release upgraded firmware for the Intellian GX-NX and the GX-NX 2 Series. This firmware and iARM should be applied to the models in Table 1 below.

It is recommended to apply this change at next service call or visit on board.

Table 1 Antenna firmware packages

No.	Product	Model Number	Previous Version	Release Version
1	GX60NX 2	V5-60G-V1Xxx	V2.02.001	V2.03.001
2	GX100NX 2	V5-11G-V1Xxx	V2.02.001	V2.03.001
3	GX60NX	V5-60G-V1xx	V2.02.001	V2.03.001
4	GX100NX	V5-11G-V1xx	V2.02.001	V2.03.001
5	GX-NX BDT	VP-T93	iARM V2.02.008	iARM V2.02.011

You can find the Firmware Package in Table 3 with dedicated download links.

Table 2 Summary

Category	Contents	Applied		Comments
		iARM	F/W	
New function	New IMU Sensor(Epson IMU G330) is supported.		✓	Refer to 1.1
Bug Fix	Switch port configuration setting does not switch in network setting. Save function updated	✓		Refer to 2.1

Table 3 Firmware Package Download Link

Product	Product	Firmware Package File	Version
GX-NX 2	GX60NX 2	V5_GX60NX2_V2.03.001.fwp	V2.03.001
	GX100NX 2	V5_GX100NX2_V2.03.001.fwp	V2.03.001
GX-NX	GX60NX	V5_GX60NX_V2.03.001.fwp	V2.03.001
	GX100NX	V5_GX100NX_V2.03.001.fwp	V2.03.001
iARM	BDT VP-T93	iARM_NX_V2.02.011	V2.02.011

Note. iARM firmware is common for all GX-NX Series BDT (GX-NX and GX-NX 2).

Details

1 New Functions

- 1.1 New IMU Sensor(Epson IMU G330) is supported due to EOL of previously supported IMU Sensor(Epson IMU G325).

2 Bug Fix

- 2.1 Go to 'Network' in 'Setup' menu. Select 'Enable' on 'Switch Port Configuration' then 'Apply'. After save & rebooting the switch port configuration is in reverted back to a default setting(Disable) status. Now it is saved as the last setting.




Figure 1 Network Setup

Contact Information

Please contact your local Technical Support team or Product Management team if you have any questions or require any additional information.

Thank you.

Product Management Team
Office: +82 31 379 1000
E-mail: PM@intelliantech.com

APAC

EMEA

AMERICAS

Release Notes



Headquarters/Innovation center

Intellian Technologies, Inc.
18-7 Jinwisandoan-ro, Jinwi-myeon
Pyeongtaek-si, Gyeonggi-do
17709 Korea

T +82 31 379 1000
F +82 31 377 6185

Rotterdam Office

Intellian B.V.
Tempelhof 12, 3045 PV
Rotterdam,
The Netherlands

T +31 1 0820 8655
F +31 1 0820 8656

Irvine Office

Intellian Technologies USA, Inc.
11 Studebaker
Irvine, CA 92618 U.S.A.

T +1 949 727 4498
F +1 949 271 4183